#### IC2000.3-1

# **Imray Correction Notice**

16 May 2012

## Chart 2000+3 WGS 84

Edition Aug 2011 Date of printing Aug 2011

The following corrections should be noted:

#### 1 Orford Ness

The stated Lt range should read 17–12M at LT HO in 52°05'·04N 1°34'·44E (ILNW 463/11)

#### 2 Orfordness

Delete Igd AIS at Orfordness lighthouse in 52°05'·03N 01°34'·46E (ILNW 56/12)

### 3 Woodbridge Haven

Move safe water Lt buoy Woodbridge Haven Mo(A)15s to 51°58'·10N 1°23'·70E.

The other buoys in the Deben entrance remain largely unchanged.

For more detailed information, mariners are advised to consult the latest sketchmap on www. eastcoastrivers.com (ILNW 173/12)  $\,$ 

#### 4 Orford Haven

Move buoys:

Orford Haven LFI.10s to 52°01'.85N 1°28'.21E

Oxley to 52°02'.15N 1°27'.80E

For more detailed information about the River Ore entrance, mariners are advised to consult the latest sketchmap on www.eastcoastrivers.com. (ILNW 174/12)